

REPORT of SURVEY for REPAIRS, &c.

Received at London Office

No. 97

Date of writing Report... 19... When handed in at Local Office... 19... Port of London

No. in Reg. Book. Survey held at 04521 on the Wood, Iron or Steel Se. Iron Baron Date, First Survey Last Survey (No. of Visits) TONNAGE Built at Pb. Glasgow By whom Russell & Co. When 1911 9 GROSS 3154 Owners E. B. Gaby Owners' Address (if not already recorded in Appendix to Register Book). NET 1985 Managers Port belonging to Oslo

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage WB=CellDBorDBa feet; uE&B feet; f total capacity tons. FPT tons; APT tons; MT feet tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 12272 Port Ams CHARACTEL. * for Special Survey. Date of last Survey and of Periodical Surveys. Years Assessed now applied. Machinery and Boiler Surveys (including date of N.B., if any). +100A1 5.31 S.S. Lya No3-1.24 BS 5.30 S.S. Lya No1-28 MS 10.27 TS 11.29 cl. Cargo balters not fitted.

WRECK SECTION No 717

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessel (State if on Felt). When put on, Month
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	Boats
Coamings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Scuppers	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Breasthooks	Rudder	Hatches	Equipment letter
Transoms	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Frames	Windlass	Caulking ditto	Cables (State if now ranged)
Reverse Frames	Have Pumps now been examined and found efficient?	Treenails ditto	length (on board) size
Longitudinals	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Rule length size
Transverses	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Floors	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Keelsons		Ditto Ditto at other places ditto	
Stringers		Stringers, Clamps & Shelves ditto	
Inner Bottom Plating		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20)	£			Fees applied for, 19
Special Damage or Repair Fee (if any) (per Sec. 20)	£			Received by me, 19
Travelling Expenses (if chargeable)	£			
Second Surveyor's Fee (if any)	£			

Committee's Minute, 19 JUL 1932 Withdraw Class & insert () Character Assigned with own. 20.7.32

Surveyor to Lloyd's Register of Shipping. General Committee Thursday, 26th July 1932

Classing Committee decision confirmed