


14 SEP 1962

Ship's Name SS/~~MS~~ "JALAKANYA" Gross tons 7180
 Is there a rpt. 9? NO Port CALCUTTA Rpt. No. 20871
 No. of visits THREE First date 25/8/62 Last date 29/8/62
 Interim Cert. issued & copy herewith? YES Damage rpt. issued & copy herewith? YES Last rpt. (H.Q. only) 20762
 Date of completing rpt. 30/8/62 Surveyed at, if different from Port above lcl.
 Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D.
 Has a Load Line Survey been held? NO Freeboard Marks verified
 State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig) 8(Eq)
 Survey fee  Damage fee Rs.100/- Expenses Rs.30/-

S.A. fee

I have surveyed the above ship in accordance with the Rules for Damage to Equipment stated sustained during a strong tide while at anchorage at Calcutta on 13th August, 1962.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. Stated lost 3 x 15 fathom length of chain cables, 1 x 8 fathom length of chain cables (Rule size 2.1/16 SQ) and a bower anchor. CSM
Replacement now done 4 x 15 fathom length of chain cable (2.3/16" ordinary) has now been supplied (See Rpt. 8 EQ) and fitted as rule size cable 2.1/16 SQ) was not available.

It is recommended that a bower anchor be supplied at the earliest opportunity.

I recommend that this ship remain as classed ~~with~~/without fresh record of dry docking subject to a bower anchor being supplied at the earliest opportunity and to all other outstanding conditions of Class being dealt with as previously recommended.

Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.


Date of Committee MONDAY - 1 OCT 1962

Minute

as now, Subject

Miner's

Miner's


 AJAY DUTTA,
 Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

003541-003548-0169

Lloyd's Register
 Foundation