

4E

Subject to

- (1) Propeller being specially examined at the next dry docking.
- (2) Screwshaft cone being examined and crack detected by 9.62 (6 months limit), (record of TS (CL) 3.62 withheld meantime).

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME..... "JALAKANYA"..... REPORT..... CAL..... No. 20762.

ES due 3.61. Partly held at previous dates. Not advanced.

MBS due 5.62. Now held.

The Surveyor reports the Starboard Boiler back header support girder found to be bent and some repairs effected but the Surveyor recommends that a note be made in the SRL Appendix relative to this item

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh record of MBS 6.62, subject as above.

SRL APPENDIX NOTE.

Insert the following:-
support girder buckled".

10.8.62.
Lloyd's Register
Foundation

