

Port BERGEN No. 4491
 Reporting Report 23/6-'58 When handed in at Local Office 23/6-'58 Received London 125 JUN 1958
 Rptd at _____ No. of Visits 2 First Date 10/8- 1958 Last Date 17/6- 1958
 Date _____

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.

No. in R.B. 24184 on the ~~Steel~~ Steel M.S. "PÆTTER" Tons gross 9109
 Built at Copenhagen By Whom BURMEISTER & WAIN When 1931- 8
 Owners A/S JENSEN'S REDERI III Owners' address (If not already in R.B.)
 Managers MARLOW WANGEN & PÆTTER CHRISTIANSEN Port of Registry ÅRENDAL
 Surveyed Afloat or in Drydock BOTH Name of Dock A/S ROSENBERG MEK. VÆRKSTED Date of last examn. in Drydock 17/6-58

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 4418 Port Bgn
 To be filled in at: Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS <small>Date of Special and of Drydocking Surveys, etc.</small>	Machinery
100A1 CARRYING PETROLEUM IN BULK 3,57 S.S. Str. (Dr) 6,56	L.M.C. P.S. 6,56 C.L.P. 3,57 St.B. 6,56 D.B.S. 12,56 S.P.S. 6,56

Give dates and references to any letters relating to this Report CLASSN(S) 8,11-57
MEMO. H 28/5-58

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined Freeboard as marked on ship and now verified ft ins
 Was a damage report made by anyone else? If so, by whom? No.

EXAMINATION AND REPAIRS AS PER RULE FOR BOTTOM.

*No repairs required due to wear and tear.
 B strake No 4 port side found indented but efficient.
 A few bottom rivets in way of indent have been caulked.
 This bottom plate should be dealt with at the next Special Survey.
 It is stated that there is no knowledge of ship having touched ground since the last docking.
 Endorsement: Indented keel plate No 9 remains efficient.*

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? YES Is Classification Certificate required? If so, to be sent to No.
 If so, is the Report sent now, or when will it be sent? Now. Has Interim Certificate been issued? YES - COPY ATTACHED AND ONE COPY HAS BEEN SENT TO THE OSLO SURVEYORS.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

It is submitted this ship is eligible to remain as classed with record of D.S. (Docking survey) 6,58 subject to indented B strake No 4 port side being dealt with at the next Special Survey.

S. A. Vide
 Surveyor to Lloyd's Register of Shipping

Date of Committee TUESDAY 22 JUL 1958

Minute DS 6.58 Subject
DBS 6.58

Noted for Header



© 2020
 Lloyd's Register
 Foundation

003591-003598-0211

TABLE 1

BOTTOM.

SURVEY

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR

Items	Now Examined		Tanks	Now Examined Internally	Now Tested
	YES	NO or NONE			
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock	YES		F.P. Tank	NO	NO
Rudder lifted	NO		A.P. "	NO	NO
Weather Decks, Superstructures and Casings	YES		D.B. Tanks (indicate Oil Fuel and Cofferdams)	NO	NO
Hatchways, Covers, closing and securing appliances	YES			NO	NO
Ventilator coamings, skylights, companionways and closing appliances	YES		Fresh Water Tanks	NO	NO
Holds	NO		Deep Tanks	NO	NO
			Oil Fuel Bunkers and Settling Tanks	NO	NO
Tween Decks	NO			NO	NO
			Side Tanks	NO	NO
Fore Peak Spaces	NO		Wing Tanks	NO	NO
After " "	NO		Other Tanks	NONE	✓
Engine Space	NO				
Boiler	NO		Cargo Tanks (Tankers)	NO	NO
Under Engines and Boilers	NO				
Funnel and Well	NO			NO	NO
Coal Bunkers	NONE		Cofferdams	NO	NO
Chain Locker	NO				
Other Spaces	NONE		Pump Rooms	NO	NO
			Have Tanks now Examined been Cleaned as Necessary?		
			Have Struts in Cargo Tanks (of Tankers) been removed?		
			Have Tanks been Retested as necessary after completion of any Repairs?		

Have the spaces now surveyed been cleared and cleaned as necessary? ✓

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules? NO

Have the bilges been cleaned out and examined? NO

Has steelwork had rust removed and afterwards been recoated as necessary? NO

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork? NO

Has a Load Line Survey been held? NO If so, state which ✓

Have the shell and deck plating been drilled as per Rule? NO. If so, Report 8(Dr) to be attached ✓

Have any alterations to the approved scantlings and arrangements now been effected? NO. If so, report details in body of Report. ✓

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—

Shell plating	GOOD	Ceiling and Cargo Battens	✓	Sluice Valves examined and found	✓
" " in way of side scuttles	✓	Cement or Asphalt	✓	Air and Sounding Pipes	GOOD
Rudder and Sternframe	GOOD	Cargo and other Hatchways	GOOD	Doubling Plates under Sounding Pipes	✓
Decks	GOOD	Hatches and closing appliances	GOOD	Masts and Rigging examined and found	✓
Superstructures and their closing appliances	GOOD	Ventilators, their coamings and closing appliances	GOOD	Condition, how ascertained (State if wedges removed)	✓
Coamings and Casings	GOOD	Companionways and Skylights	GOOD	Chain Locker	✓
Beams and Fastenings	✓	Shell Openings	GOOD	EQUIPMENT	
Frames	✓	Ash Shoots	NONE	Equipment Letter	✓
Reverse Frames	✓	Overboard Discharges and Scuppers	GOOD	Anchors, No. of	✓ Condition ✓
Longitudinals	✓	Freeing ports	✓	Cables (State if now ranged and examined)	NO
Transverses	✓	Steering Gear (Main and Auxiliary) examined and found	GOOD	" length (on board)	✓ mean diam. ✓
Floors	✓	Windlass examined and found	GOOD	" Rule Length	✓ Size ✓
Keelsons	✓	Pumps " " "	✓	Hawsers and Warps	GOOD & SUFFICIENT
Stringers	✓	W.T. Doors " " "	✓	State if any Anchors or Chain Cable have now been supplied or retested, if so, complete Report 8(Eq) and attach.	NO ✓

Have conditions (A) or endorsements (B) of Class (if any) been dealt with (A) YES (B) NO See Below

REMARKS, REPAIRS, Etc. (Contd.)

Survey Fee 250.-

Special Damage or Repair Fee (if any) ✓

Travelling Expenses (if chargeable) 50.-

Second Surveyor's Fee (if any) ✓

Date when A/c. Rendered 21/6-58.

Lloyd's Register Foundation