

" ROCKLEAZE "

Italics note at present in List of Endorsements -

"4 stoppered tubes to be renewed next BS".

If stoppered tubes are not renewed at the B.S., the stoppers must be withdrawn and examined for efficiency before being refitted.

In this case the stoppers have been renewed at each B.S. 1954, 1955 and 1956. They are, therefore, efficient until next B.S., when they will either be examined and found in order or renewed again, unless the tubes are then renewed. All that is required is a note in italics for information of Surveyor at next B.S.:-

"4 boiler tubes fitted with stoppers"

*Note for
S.R.L. Appendix*

lwl

15th May, 1958

*Noted for S.R.L.
DND
16.5.58*

SM

16.5



© 2020

Lloyd's Register
Foundation

003605-003610-068
003605-003610-0110