

Team Pr  
in Mail  
in Donl

31.

1E

14 JUL 1933

ed by Chief Engineer Surveyor \_\_\_\_\_

Received from Chief Engineer Surveyor \_\_\_\_\_

SEL'S NAME Parkwood

Rpt. Sl. 5-3396  
Ld.  
Sl. No. 18405-  
31245-

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22).

Type of Engine T. 3 Cy. 13 1/2", 23" & 38" — 27"

If Boilers fitted with forced draught

No

Tail Shaft. If fitted with a continuous liner

Yes

If fitted with an outside gland of }  
approved type

No

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed F L M C 7.33

1 SB 200 lbs.  
DB 125 lbs.

L. J.  
14/7/33.

Al.



© 2021

Lloyd's Register  
Foundation

003620-003624-0471

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

If Sockets, etc. Mechanical Tests

14001

1E

1888

Received from Cash

1000

1000

1000

© 2021 Lloyd's Register Foundation



© 2021 Lloyd's Register Foundation

1000 - 1000 - 1000

1000 - 1000 - 1000

1000 - 1000 - 1000

1000 - 1000 - 1000

1000 - 1000 - 1000