

port made by anyone else? If no, by whom?

personally go inside each Main Boiler separately and make a thorough examination at this time?

12 DEC 1943 4 E

Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

IE

Onelina

REPORT

Yre

No.

1530

The Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

sement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and
ing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH *enemy action*

*any repairs have been effected to the pumping arrangements in way of
to Starboard Side Tanks*

*to Class is Subject to aft (main) of intermediate shaft being examined before end of 11/43
weyer states he has examined the part now (5.43) & there is no change in its condition since
it is in 11/42. It should be requested to state whether this special condition may now be
whether further examination is necessary.*

*Request to aft (main) of intermediate shaft being examined before end of
11/43 & the permanent repairs being effected to pumping arrangements
(See also Ship's endorsement 30.11.43)*

003631-003639-0172

1.12.43

examined internally and externally and found good.