

Ship's name

"LODESTONE"

Port

Mtl.

No. 14906

Last survey date 13.9.62.

Class is subject to

indented shell plate No.8 in 3rd strake below sheer (s.s. from aft) and structure in way being specially examined and dealt with as necessary next drydocking.

ACTION is DEFERRED for examination in dry dock for possible underwater damage.

S.R.L. Appendix (as before ~~xxxxxxxx~~)

Nature of present survey (afloat and ~~in drydock~~)

Temporary repairs on account of damage due to striking quay wall.

Recommendation

SUBJECT as above, and to indented shell plates No.3 etc. in 1st below sheer (p.s.f) and Nos.2 & 3 in 2nd below sheer (p.s.f) being examined and dealt with as necessary next drydocking but ACTION continue to be DEFERRED for examination in dry dock for possible underwater damage.

SUBJECT

IN S.R.L.
Drydocking(contact).

IN S.R.L. APPENDIX.
Shell plates M.7 (p.s. from fwd) and A.4,B.5,C.5 (s.s. from aft) indented.



© 2020
W.P.T.

10/10/62.

Lloyd's Register
Foundation