

Date of writing Report 20/8/57.

When handed in at Local Office

Received London

Survey held at Fleetwood.

No. of Visits 2

First Date 16/7/57 19

Last Date 9/8/57 19

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

25450

S.S. on the Iron or Steel M.S.

S. T. " RED DRAGON "

Tons gross 377

Year Month

When 1930 3

Built at Selby.

By Whom Cochrane & Sons Ltd.

Owners Iago Steam Trawler Co. Ltd.

Owners' address

(If not already in R.B.)

Managers E.D.W. Lawford.

Port of Registry London.

Surveyed Afloat or in Drydock Afloat.

Name of Dock Wyre Dock.

Date of last examn. in Drydock -

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No.

To be filled in at Head Office.

Port

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report -

SHIP'S CLASS
Date of Special and of Drydocking Surveys, etc.

Machinery

+ 100 Al. 1,57.

+ LMC.

steam trawler.

ES. 2,54.

SS. Flt. (Dr) 2,54.

MBS. 6,56

TS(CL). 1,55

SPS. 3,54.

ND.

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined -

Freeboard as marked on ship and now verified - ft - ins

Was a damage report made by anyone else? If so, by whom? -

EXAMINATION AND REPAIRS AS PER RULE FOR ANNUAL EXAMINATION OF ROD AND CHAIN STEERING GEAR.

Steering gear examined together with blocks (opened out) springs, chains (fired) and channel guides.

Repairs (W & T) :- 1 length of chain (worn) now renewed of tested material.

Channel guides part renewed (p&s) as necessary.

On completion steering gear examined under working conditions and found satisfactory.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Fairied or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship?

Yes

Is Classification Certificate required? If so, to be sent to

No

If so, is the Report sent now, or when will it be sent?

Now

Has Interim Certificate been issued?

Yes.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey, for example:— "to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This vessel as now seen is in good condition and eligible in my opinion to remain as now classed without fresh record of survey.

Surveyor to Lloyd's Register of Shipping

Signature of Committee

Minute

Noted for Header



© 2021

Lloyd's Register Foundation

003742-003749-0075

