

WOKINGHAM COPY.

REGISTER
GLASGOW

(3.8.44)

CHESHIRE YOUR LETTER FIRST INSTANT PROPOSED METHOD
OF REPAIR PORT SHAFT CAN BE ACCEPTED PROVIDED
SURVEYORS ENTIRELY SATISFIED STOP LINER OF STARBOARD
SHAFT SHOULD BE CUT BACK AS INDICATED IN PENCIL ON PLAN
AND SURVEYORS SHOULD SATISFY THEMSELVES BY MEANS MAGNETIC
CRACK DETECTOR OR SIMILAR MEANS THAT DEFECT DOES NOT EXTEND

© 2020
Lloyd's Register
Foundation

003769-005777-0089 1/2

WOKINGHAM COPY.

GLASGOW

BELOW BOTTOM OF GROOVE

COMMITTEE



© 2020

Lloyd's Register
Foundation

0039²