

Received from Chief Ship Surveyor

29 JAN 1960

SHIP'S NAME "REGENT HAWK" REPORT Trd. No. 1650

3  
Outstanding Conditions of Class: NONE.

R.L. Appendix. (As before ~~xxxxxxx~~)

Structure of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs to shell plate E.7 in way No.4 cargo tank (p.s.)  
on account of leakage.

Recommendation:

SUBJECT to shell plate E.7 (fractured) in way No.4 cargo  
tank (p.s.) being specially examined and dealt with  
as necessary next drydocking.

As Now. Subject

IN S.R.L. APPENDIX.

E.6 & 7 (s.s.) and E.7 (p.s.) indented.



*Attchd  
28/1/60*  
© 2020

Lloyd's Register  
Foundation