

Received from Chief Ship Surveyor..... 14 NOV 1957

SHIP'S NAME "REDRIFF" REPORT Nwc. No. 114786.
JD.

Outstanding Conditions of Class: Subject to set in side shell
plating, etc.(s.s.) abreast No.1 hatchway being dealt
with as necessary by next drydocking.

ACTION is DEFERRED for examination in drydock
after contact with submerged buoy.

Endorsement of Certificate (~~As before~~ or None)

ature of Present Survey: (Afloat and in dry dock)

Docking. Damage repairs (collision). Wear and tear
repairs and repairs to deferred item above.

Recommendation:

SUBMITTED record of "DS 10,57" be
assigned, without special condition.

DS 10,57. Without.

DELETE FROM S.R.L.
Drydocking (sub. buoy).



© 2020

Lloyd's Register
Foundation

Blk (new)

Have the Tanks been tested ?	No	Air and sounding Pipes	Not	Sealing	State if examined	Standing a
		Doubling Plates under Sounding Pipes				Sails

005788-005799-0041