

Metals
Permanente Corp. (Shipyard No.1), Richmond, Cal.

Yard No. 2136.

Liberty ship of the EC2-S-C1 type.

Present to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME s.s. "DAULTON MANN" REPORT Bal. No. 8468

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

WRECK SECTION

Nature of Survey S.S. for Classification and ~~When due~~ Repairs.

This vessel was built in 1944 and classed with the American Bureau of Shipping.

Classification with this Society is desired.

Plans of midship section and general arrangement for this type of vessel have been examined at this Office and the scantlings and arrangements found suitable for the class 100A-.

For further particulars see Circular issued May 1946 and endorsement 8.5.47 with First Entry Report on "PIONEER".

The BALTIMORE Md., Surveyors on a First Entry Report and Rpt 8, report (3.47) the scantlings and arrangements verified, the requirements for Vessels Not Built Under Survey and of a Periodical Special Survey complied with.

A hinged watertight door is fitted for access to the shaft tunnel and it is recommended same be altered to comply with the Rules at the first opportunity.

Structural reinforcements etc., as required for "SAM" ships have been provided.

"Subject to tunnel watertight door being altered to comply with the Rules at the first opportunity."

100A1 "Carrying oil ~~in~~, FP above 150°F in deep tanks" "Fitted for oil fuel FP above 150°F".

3.47 Bal.
S.S. Bal.-3,47.

Classed 3.47.

2 Dks "Elec. welded"
Cell DB 368' 1256t, DTa 20' 767t, DTsf 61' 648t, FPT 138t, APT 152t.
FK, 7BH, pt. Cem.
O.L. 441.5'
E.S.D.
2 1/2"



Equipment letter for fees: "at" in red.



Lloyd's Register Foundation

003800-003807-062

31.7.47.

Are Frame and Reversed Frame) Floors E.W. to shell and inner bottom

Bridge Deck, Angle, [or [