

COPY

Ship's name "MULBERRY HILL" Port Lgs. No. 3971

Last survey date 3.12.64.

GB Class is subject to a bower anchor and 60 fms. of chain cable (supplied Gib.9,64) being verified with certificates at the earliest opportunity.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Damage (contact) involving side shell plating (s.s) in way of F.P.tank - temporary repairs.

Recommendation

SUBJECT as above, and to damaged side shell plating etc. in way of F.P.tank (s.s) being specially examined and dealt with as necessary next drydocking.

As Now. Subject
IN S.R.L. APPENDIX.

- Lower stem bar set over to port.
- Bottom shell plating slightly corrugated.
- Shell plates A.5 & B.1(p.s.a), A.4(p.s.f) & stern wrapper plate indented.
- F.9, E.9 & 10 (s.s.amids) slightly wavy.
- Shell plates G.5 and H.5 (p.s.f) indented and wavy.

© 2020

Lloyd's Register
Foundation