

COPY

Ship's name

"MULBERRY HILL"

Port

Chg

No.

410

Last survey date

4.7.63.

GB

Class is subject to

NONE.

S.R.L. Appendix (as before ~~or none~~)

Nature of present survey (afloat and in drydock)

Damage (contact) involving side shell plating in way of No.2 hold(p.s)

Recommendation

SUBJECT to riveting of shell plates in 'D' & 'E' strakes between frames 105/115 in way of No.2 hold (p.s) being specially examined and dealt with as necessary next drydocking.

As Now. Subject

IN S.R.L. APPENDIX.


Lower stem bar set over to port.

Bottom shell plating slightly corrugated.

Shell plates A.5 & B.1 (p.s.a), A 4 (p.s.f)

and stern wrapper plate indented.

F.9, E.9 & 10 (s.s. amids) slightly wavy.



© 2020

Lloyd's Register
Foundation

003808-003815-0184