

23 JUL 1963

Ship's name "WAIRANGI" Port Ham No. 12673

Last survey date 31.5.63.

GB Class is subject to 15 fathoms of chain cable being supplied at the earliest opportunity.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Nature of present survey (afloat and ~~xxxxxxx~~)

Damage (H.W.) involving shell plates H.1 (s.s), G.1 (p.s) from forward - temporary repairs.

Recommendation

SUBJECT as above, and to shell plates H.1 (s.s), G.1 (p.s.) from forward (E.W. and part doubled 5,63), being specially examined and dealt with as necessary next drydocking.

As Now. Subject

IN S.R.L. APPENDIX. (Extended SS)

Stem and stem plating (p.s.f) indented.

Shell plates K.11 and L.11 (p.s. from fwd) indented.

The Surveyors refer to a condition of class placed against the ship by the Buenos Aires Surveyors 25.4.63 - permanent repairs have been effected and it is recommended the Buenos Aires Surveyors be requested to expedite their report.

C.S.S. Records Dept.
to note.

003816-003823-0107

now

See BA-35009
35009

S/S
12/7/63.