

£ 15.0.0 (Repairs)

£ 1.10.0 (Repairs)

COPY

W/S 832

Ship's name

"WAIRANGI"

Port

Ham

No.

12673

Last survey date

31.5.63.

GB

Class is subject to

15 fathoms of chain cable being

supplied at the earliest opportunity.

S.R.L. Appendix (as before ~~or none~~)

Nature of present survey (afloat and ~~in~~ drydock)

Damage (H.W.) involving shell plates H.1 (s.s), G.1 (p.s)
from forward - temporary repairs.

Recommendation

SUBJECT as above, and to shell plates
H.1 (s.s), G.1 (p.s.) from forward
(E.W. and part doubled 5,63), being
specially examined and dealt with as
necessary next drydocking.

As Now. Subject

IN S.R.L. APPENDIX. (Extended SS)

Stem and stem plating (p.s.) indented.

Shell plates K.11 and L.11 (p.s. from fwd) indented.

The Surveyors refer to a condition of plates
placed against the ship by the Buenos Aires Surveyors. As
permanent repairs have been effected and it is recommended the
Buenos Aires Surveyors be requested to expedite the repairs.

C.S.S. Record
to note.



Lloyd's Register
Foundation

End. S.1

Now 12/12/63

SPL FOR

003816-003823-0117