

13 SEPT 1957 ^{4E}

by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

S NAME "ROTULA"..... REPORT Yka. No. 2318.

C.S. Advanced.

Docking. Screwshaft seen.

DBS due 5.57, now held.

The forward pump room sea valves port and starboard found holed, now replaced by cast iron valves and the Surveyor recommends these valves be renewed in steel by 6.58.

The Rule requirements for cast steel sea connections was not in force at the time this ship was built and as the Rule is not retrospective, the Surveyor is not in order in recommending a condition of class.

IT IS SUBMITTED that this vessel is eligible for THE RECORDS, DBS 7.57, TS 6.57. (CL) *without special conditions*

Env

12.9.57.



© 2020

Lloyd's Register
Foundation

003824-003831-0185