

Received from Chief Ship Surveyor

3 - JAN 1961

SHIP NAME

"SUNETTA"

REPORT

AMS  
LON

23832  
No. 143734

Standing Conditions of Class:

SUBJECT to sternframe solepiece (E.W. 1,53  
7,56 and E.W. & reinforced 11,53) also to rudder post at  
top (E.W. 7,56) being specially examined at the next  
drydocking.

L. Appendix. (As before ~~or None~~)

Condition of Present Survey: (Afloat and in dry dock)

Wear and tear repairs.  
Provisional Survey for estimating cost of  
repairs for the Special Survey.  
Examination afloat after grounding subsequent to  
above drydocking. Contact damage repairs.

Recommendation:

IT IS SUBMITTED the ship is eligible to remain as classed,  
and have record of DS 10,60 assigned as recommended, subject  
as above but further ACTION be DEFERRED for examination  
in dry dock after grounding.

DS 10,60 Subject.

INSERT IN S.R.L.  
Drydocking (grounding).

IN S.R.L. APPENDIX.  
Indents in a few shell plates (p & s).  
(Rudder post gudgeons slightly out of line.)

**SHIP RESEARCH DEPT.**

**TO NOTE**

lk (new)



P.T.O.



© 20 Lloyd's Register  
Foundation  
C.S.S. Records Dept.  
to note.

003838-003845-0070

IT IS FURTHER SUBMITTED the Amsterdam Surveyors  
be advised it is concluded the "drillings"  
forwarded at this time have been obtained by  
the Ultra Sonic testing method, and that check  
drillings have been made in accordance with  
Circ. No. 2111

They should be requested to forward particulars  
of the check drillings for reference.

*See letter dated 15/13/60*

*1/6/11*

*S. H. G.  
12/12/60*



U.S. Records Dept.  
to note



© 2021  
Lloyd's Register  
Foundation