

1E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Sunetta

Rpt.

Rr:

No. 23510

Ans.

13335

is of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

of Engine

Pie Engines 4 S.C.S.A.
8 Cy. 25 $\frac{7}{8}$ " — 55 $\frac{1}{8}$ "

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of }
approved type

No main boilers

Yes

No

This vessel's Machinery appears to have been built in accordance
the Rules and the approved plans, and it is submitted she is

beable to be classed + LMC 2.35

DB 180 th.

© 2021



Lloyd's Register
Foundation

005838-005845-0053

© 2021

Lloyd's Register
Foundation



Sum

50

七

and

Reg

recu

beer

五

be

J. H. Deane

Wm. Webb

While
underst