

of Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

ME "WSPOLPRACA"

REPORT

Ant.

No. 34121

4E

Some cracking noted in way of the forward main bearing cast iron support and bed plate. It was not possible to fully examine the pairs with the engines in position and it is stated that the vessel being towed to Poland where it is understood the ship's future service will be decided upon.

The Surveyor recommends that the main engines be not used until repaired.

IT IS SUBMITTED action be deferred pending further information.



© 2021

14.9.56.

Lloyd's Register  
Foundation

003858-003866-0058

