

"CIS BROVIG"

Before this case receives consideration IT IS SUBMITTED the Greenock Surveyors should be asked whether they opened out and examined the oil engine driving the 50 KW generator, and whether they obtained the necessary particulars so that the scantlings of the crank shaft may be considered.

At the same time, they should be asked to confirm that the donkey boiler shell plating is of 29/33 ton steel and not 28/32 as reported.


Further, they should be asked which pump is the standby fresh water circulating pump for main engine. It would be appreciated if such information could be given in all future cases.

Makers' test certificates covering the electric generators do not appear to have been received & should be forwarded as soon as possible.

see file, 11/11/48

Ent.

© 2020



21. 10. 48.

Lloyd's Register
Foundation

003895-003905-0030