

"KOEI MARU"10.61 Shimomareki

Small cracks in feet of all main engine connecting rods temporarily repaired by welding.

3 mos limit till 2.62

11.61 Shimomareki

Repairs examined and remain efficient

New rods on order, to be fitted when available

5 mos. limit till 4.62

4.62 Kobe letter


Ship sold. New Owners do not intend to renew rods because ship will "ultimately" be scrapped.

Date for scrapping not yet decided

Ship apparently laid up mesuride.

Although welded repairs to forgings of this kind are not accepted as permanent, it is considered that in this case, in view of the position and extent of the cracks the repairs could be accepted for a few years with intervening inspections at 6-monthly intervals, pending renewal of the rods.

Outstanding fees.



list. © 2020

Lloyd's Register
Foundation

003948-003957-0105

FRIDAY - 4 MAY 1962

Defer two weeks
Rmt.

FRIDAY 18 MAY 1962

2 to broken up
Rmt.

ADDED FOR
REISING



© 2020

Lloyd's Register
Foundation