

Received from Chief Ship Surveyor

27 JUL 1953

ME "RANELLA"

REPORT

Ams.

No. 18929

ing Conditions of Class:

Subject to the indented shell
ing etc. (p.s.) in 2nd strake belows sheerstrake in No.3 cargo tank
dealt with at the next drydocking, and to 15 fathoms of
cable being supplied at the earliest opportunity.

nt of Class (B) (~~As before~~ None)

Present Survey: (Afloat and in dry dock)

ing: Damage repairs (H.W.) to indented shell plating,
(p.s.) as above.

ation:

SUBMITTED record of docking 6,53 be assigned,
subject to 15 fathoms of chain cable being supplied
at the earliest opportunity, but without other condition.

Ams. Subject
Without.



© 2020

Lloyd's Register
Foundation

003958-003963-0270