

... of any letters respecting this case... to be briefly summarised at the end of the report. State also the dates and other causes; and besides

A.S. 3.52
MCHY AFT.
ELEC WELDED.

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

23 FEB 1953 4E

NAME "BRAYWICK"

REPORT

Lon.
Sou.

No. 126309.
126309.
21587.

... remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Survey REPAIRS - TO - ENGINES - AND - BOILERS - DUE - TO - DAMAGE - THROUGH

Docking. A cracked cylinder head renewed.

IT IS SUBMITTED that this vessel is eligible to remain as classed.



© 2021
20. 2. 53.

Lloyd's Register
Foundation



slater bush, and outside gas valves, all found in good

003980-003984-0061