

HESPERIA

No. in Reg. Book. *Survey held at* _____ *Date, First Survey* 22nd March *Last Survey* 29th April 1921
(No. of Visits 13)

on the ~~Wood, Iron or Steel~~ S.S. "~~PATRIA~~" now renamed "HESPERUS" Master F. H. Peterson - 21

4503

TONNAGE:—	Built at	Flensburg.	By whom	Flensburger Schiffbau Ges.	When	1919	YEAR.	MONTH.
GROSS 3422	Owners	British & S. American Steam. Co. Ltd. (R.P. Hanson & Co. Mgrs)	Port belonging to	Liverpool.				5
UNDER DEK. 3630	Owners' Address							
NET 2406	(if not already recorded in Appendix to Register Book).							

Surveyed Afloat or in Dry Dock? Both Name of Dock Ct. Bailey's Dry Dk. Destined Voyage?

WB=CellDBorDBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons. precisely as in Register Book & Supplements).

<p>N.B.—All alterations in the existing records should be <u>underlined</u>.</p> <p>If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, <u>and the insides of the tanks examined</u>. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, <u>sideways</u>, and of the inner bottom plating, especially in the boiler space.</p>		<p>CHARACTER.</p> <p>★ for Special Survey.</p> <p>Date of last Survey and of Periodical Surveys.</p>		<p>X certified how long</p>	<p>Machinery and Boiler Surveys</p> <p>(including date of N.B., if any)</p>
---	--	--	--	-----------------------------	---

Last Report, No. _____ *Port* _____ *FE attached*

(Periodical surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as
 painted on Ship and now verified } ft.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? _____ Was a damage report made by anyone else? If so, by whom? _____

REPAIRS, OR EXAMINATION AS PER RULE, FOR Part Survey (S.S. No. 3.) for Classification as per Section 48.

Vessel placed in Dry Dock: bottom examined, cleaned & recoated. Rudder lifted & examined. Cables ranged & cables & anchors examined. Marking compared with certificates. Holds & tween-decks, Fore-peak & fore-peak tank, bunkers, decks, deck-openings & erections, steam steering-engine, gear & connections, windlass, ventilators & coamings, hatchways & hatches & supports, masts, spars & rigging, chain-locker & shell-plating in way of sidelights & ash-shoots, stokehold & tunnel W.T. doors, and Engine & boiler spaces now examined & all found in good & efficient condition. Nos 1, 2, 5 & 6 double-bottom ballast tanks & after peak tank tested under pressure & found in good order. Air & sounding pipes to same examined. (No ceiling on tank-top). Scantlings verified (see 1st Entry Report attached).

SUMMARY OF DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed	...								
Removed and Fair'd or Repaired	...								
Fair'd or Repaired in place	...								

PRESENT CONDITION OF THE		Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Good	Inner Bottom Plating	Engine Room Skylights	(State if on felt.)
Caulking of Decks	"	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month
Waterways	"	State if Tanks now tested	Scuppers	Boats
Coamings	"	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	"	Ceiling	Hatches	Condition, how ascertained
Outside Plating	"	Cement or Asphalt	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	"	Rudder	Caulking ditto	Sails
Rivets	"	Steering gear and its connections	Treenails ditto	Equipment letter
Breasthooks & Crutches	"	Windlass	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	✓	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Good	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	„ length
Reverse Frames	"	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	„ Rule length
Floors	✓		Stringers, Clamps & Shelves ditto	Hawser & Warps
Keelsons	✓		Salting ditto	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

The vessel is in a good efficient condition it is recommended that she be classed 100A1 Shelter Dr with freeboard, with notation of SS Npt No 3, subject to completion as above.

Survey Fee (per Section 28)	£	:	:	Fees applied for,	
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	Received by me,	
Travelling Expenses (if chargeable)	£	:	:		
Second Surveyor's Fee (if any)	£	:	:		

60

1887
17.9.10

ST. Bryden

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

FRI. 10 FEB. 1972

See minute on Dec 8 24 26

FRI. 29 SEP. 1922

TUE 24 APR 1923

© 2020

Lloyd's Register
Foundation

004062-004066-0119

issued 21/9/21

the Certificate required? If so, to be sent to

F.B.—If this Report is copied by Corving Press, especial care must be taken that the corving paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

8th. Anchor shank (fractured) now renewed, anchor retisted.

To Complete Special Survey.

Fore peak tank & Nos 3 & 4 double-bottom tanks (under engines & boilers)

Bulb-angle coannings complete with covers, etc. to be fitted to 4 escape-holes

Shelter-tween-Deck Bunkers.

It is the wish of the Owners that this Survey should be counted as S.S. No. 3.

જા. ૮.

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]