

13 OCT 1965

SL Ship's name "E. MYRTIDIOTISSA" Port OFF No. 62806
Class is subject to Last survey date 22.9.65

For conditions of class see previous endorsement.

ACTION DEFERRED for examination in drydock after grounding.

S.R.L. Appendix ~~(as before or none)~~

Nature of present survey (afloat and in drydock) ~~xxxxxxxxxxxxxxxx~~

Equipment:- Loss of bower anchor and 8 lengths of chain cable.
Supply and verification of a bower anchor and
9 lengths of chain cable including part deferred
item as above. Permanent repairs to damage (HW)

Recommendation

SUBJECT to midship deckhouse fwd. plating (s.s),
stiffening and coaming bar being permanently repaired
by 10.65 to ²boat deck beams fwd and to shell plating
in 2nd and 3rd ^{8/65}sheer abreast fore end of No.2 hatch
(s.s) and framing in way being specially examined and
dealt with as necessary next drydocking, but ACTION
continue to be DEFERRED for examination in drydock
after grounding, without special conditions.

Subject ~~amended~~.
Without.

IN S.R.L.
Drydocking (grounding).

