

Chief Surveyors.....

Received from Chief Surveyors.....

15 JUL 1943

VESSEL'S NAME "HALVARD BRATT" REPORT Gls No. 67331

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Part of Survey Completion of Examined L.R. 5.43. When due

Permanent repairs are required to indented shell plates D.5 & E.6 & framing in way (p.s.) and to (fractured) stem plate at the Owners' convenience, to indented shell plating (p.s.f.) at the first opportunity, and the rudder mainpiece E.W. & reinforced 5.43, requires to be specially examined at the next dry docking, also to (a bower anchor being supplied).

"Examined L.R. 5.43," Bry.



© 2020

Lloyd's Register
Foundation

004238-004248-0140