

D REPORT on the

S. S. "Louisiana".

This submitted the Jøthenburg Surveyors be informed that from their letter dated 3rd inst. it would appear that two complete loadline dies with their accompanying seasonal lines are marked on the vessel's sides, although no mention was made of this in their verification of marking form dated 73.12.26.

They should be informed that ~~this is not permissible for such marking to be made and~~ as freeboard is a condition of the vessel's class only one die should be marked and the centre of this die must be in accordance with the freeboard approved by the Committee viz $2'-8\frac{1}{2}"$ below shell upper deck at side. They should arrange ^{if possible} for the marking to be amended and forward full particulars to this office.

The Oslo Surveyor should be advised.

06/1/27 J. M. W.

BH

6.1.27