


X

Falla de desvío del compás patrón del
vapor argentino "Sud" levantada después
de hechas todas las instalaciones

Ref	δ	Ref	δ
N	-1	S	+1
N10E	-4	S10N	+3
N20E	-5	S20N	+5
N30E	-7	S30N	+7
N40E	-8	S40N	+8
N50E	-9	S50N	+10
N60E	-10	S60N	+11
N70E	-11	S70N	+12
N80E	-11	S80N	+12
E	-11	N	+12
S80E	-11	N80N	+10
S70E	-10	N70N	+10
S60E	-9	N60N	+8
S50E	-8	N50N	+7
S40E	-7	N40N	+5
S30E	-5	N30N	+4
S20E	-3	N20N	+2
S10E	-1	N10N	+0



Lloyd's Register
Foundation

004308-004313-0170

there any joints in or branches from the cable leading from dynamo to main switch board. No ✓