

COPY

Lloyds

SURVEY ON SHIP.

10071

I William Alexander DOUST, Special Officer
We of The Salvage Association

Certify that at the

request of Messrs. Frank G. Strick & Co. Ltd.

Lloyd's Agents at Oran (Algeria)

I surveyed the s.s. "AFRICAN MARINER" on the 3rd. & following days of January
We

last, in consequence of her having been struck by bomb splinters during an air
raid at Barcelona on the 5th. of the December 1938.

On examination of this vessel on the day named I found the damage reported in the
certificate granted by Lloyd's Agents We at Barcelona to be correct, with
the exception of an omission of the fore peak electric light cable
which was cut by a splinter and the fusing of which caused a short on
the main switch board.

I have recommended that the said splinter holes in
the hull be suitably welded up. The electric light cable to the fore
peak be renewed. The switch board of the Main Dynamo be tested by an
electrician and proper fuses fitted, the wiring from the stokehold
to the alarm be attended to. The starboard lifeboat be suitably
repaired and the woodwork of the wing of the flying bridge be

I also saw the diver going down to examine the vessel's bottom, and he
We refitted also the starboard light screen to be fitted to B.O.T.
regulations. The whistle pipe to be suitably repaired.


reports: That he examined her bottom, and that he found

From the survey that I have been able to make, as far as possible, We
conscientiously believe the said vessel can proceed on her voyage.

Dated Oran, 7th. January 1939

Surveyor appointed by Lloyd's Agents.

W. A. Doust



© 2020

Lloyd's Register
Foundation

004382-004386-0160

004382-004386-

No endorsement
to await report from
Barcelona.

~~if not~~ ~~by~~ ~~1978~~



© 2020

Lloyd's Register
Foundation