

19 FEB 1960

Received from Chief Ship Surveyor

SHIP'S NAME "NORMANBY HALL" REPORT Dub. No. 8835

VC

Outstanding Conditions of Class: SUBJECT to indented shell plating (p.s.f) and sheerstrake plates Nos. 6 & 10 (s.s. from aft) being dealt with as necessary at the Special Survey.

R.L. Appendix. (As before or None)

Nature of Present Survey: (Afloat and in dry dock)

Permanent repairs to damage caused by contact.

Recommendation:

SUBMITTED record of 'DS' 2.60' be assigned as recommended SUBJECT as above.

DS' 2.60. SUBJECT.


IN S.R.L. APPENDIX.

Indents in bottom and side shell plating etc., Bottom slightly set up. No.9 sheerstrakeplate and stringer plate and bar in way slightly indented (s.s.)

IT IS FURTHER SUBMITTED the Surveyors be advised it is concluded that the rudder main piece was renewed in test material at this time, but this might be confirmed.

Blk (new)

X
26/2



© 2021

Lloyd's Register Foundation

29/2/60

ABM
17.2.60

004387-004393-0027