

5e, 10, 40.

1

Barclay Curle & Co. Ltd., Glasgow.

Yard No. 691

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME Twin sc. m.v. "SOCOTRA" Report Gls. No. 67107

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey First Entry

This is a complete superstructure vessel and her scantlings are suitable for a draught not exceeding that of a C.S.S. vessel.

The tank top plating has been increased under the hatchways in lieu of ceiling.

Openings in ^{six} the divisional watertight bulkheads in the Shelter 'tween decks are closed by steel plates with special hook bolts, as approved in this instance.

LOCAL "With freeboard" "Carrying vegetable oil in wing tanks amidships".

1 Dk & Shelter dk, 3rd deck except in No.5 hold.

Cell DB 392' 1392t, wing tanks amidships 204t, FPT 73t, APT 142t

FK, 7BH (Coll Sh dk, 6 to 2nd dk) ~~6 divisional W.T.BHs in Shelter~~ ^{1/18.6.43} decks, Lloyd's A & CP

F 48'

O.L. 485.5'

E.S.D.

d
23
16

The class is assigned and maintained upon the understanding that the equipment ^{of Anchors} will be made to accord with the requirements of the Rules when the present state of emergency has passed, and that hatch covers at the 3rd deck and cargo battens will be fitted at the first available opportunity.

Insert in S.R.L. (A bower anchor to be supplied).

Hatch covers at 3rd deck and cargo battens to be fitted at the first opportunity.

T.O. CLOSED, (W.E.)



© 2021

Lloyd's Register
Foundation

31. 5. 43.

004440-004449-0025

Angles

Hoop Deck, Angle, L of

Spacing