

Steam Pressure -
In Main Boilers - 200 lb

If Surveyed Afloat & in Dry Dock - Durban
(State Name of Dock.)

Particulars of Classification (w
precisely as in Register Book

30 APR 1952 3E

Received by Chief Engineer Surveyor Received from Chief Engineer Surveyor

VESSEL'S NAME "CHARLES WHYTOCK" REPORT Drb. No. 5847

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report. 24/5/52.)

Nature of Survey SPECIAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD FOR S-S- No.

LMS
LMS(M)- due 2.52 , partly held now.
MS
BS

~~now-further-advanced-and-the-following-repairs-effected-(due-to~~
Docking. Screwshaft drawn. Liner found open at joint in centre and shaft found grooved in way. Screwshaft renewed and stern bush re-wooded.

It is proposed to complete the survey - not stated.

It is submitted that this proposal merits approval and the vessel is eligible to remain as classed, and WILL BE eligible for the record Blr.S 3.52 when the survey has been completed, S(N) 2.52 now.

The following remains to be done to complete the Survey -
Boiler to be examined under steam, its safety valves adjusted, and the oil fuel and steam smothering installations examined under working conditions.

29. 4. 52.



© 2021
FOR C.E.S. RECORDS
Lloyd's Register Foundation

004440-004449-0188