

004677-004680-0295 1/2

SHIP'S NAME **AI HUSAINI**

PORT **Jck.** No. **2918**

LAST SURVEY DATE **24. 2. 66**

CLASS IS SUBJECT TO

Propeller being specially examined at next dry docking.

Repairs to boilers on account of leakage. Surveyor shall order 8 fine sides of boiler to be credited to next MBS due 6.66.

It is submitted that the vessel **WILL BE** eligible for the record MBS 2.66 when the survey has been completed.

subject to done
by 12/5/66

To complete MBS

air heaters to examine, mounting & fittings.
safety valves to examine, safety valves
to adjust, boiler securing arrangement
to examine, oil burning system & vents
cables to examine in accordance with
the Rules

(2)

SHIP'S NAME

Al Husaini

PORT

No.

LAST SURVEY DATE

Yes - 25.7.66
R.

CLASS IS SUBJECT TO

It is concluded that superchargers were examined as this is part of water-side of vessel but surveyor should confirm. The surveyor in future similar cases, complete the section covering boiler surveys and state what is outstanding for completion of MBS. The surveyor in this case should state dates of last internal inspection of each boiler and issue an amended certificate stating what remains to complete the boiler survey.



© 2021

Lloyd's Register
Foundation