

Ship's name

"AL HUSAINI"

Port

Bal

No. 12784

Last survey date 29.3.65

GB

Class is subject to

previous endorsement.

For conditions of class see

S.R.L. Appendix (as before ~~xxxxxxxxxx~~)

Nature of present survey (afloat ~~xxxxxxxxxxxxxxxx~~)

Temporary repairs to H.W. damage.

N O T E D.

Recommendation
~~xxxxxxxxxxxxxxxx~~

SUBJECT to a bower anchor and 30 fathoms of chain cable (reported placed on beard Bal.3,65) being coupled up and verified with certificates on ship's arrival at a home port, and to indented shell plating in 1st & 2nd strakes below sheer (s.s) in way of aft end of No.1 'tween deck being specially examined and dealt with as necessary next drydocking (Deferred S.S.Repairs) and to wasted rudder trunk plating being specially examined and dealt with as necessary by 4,65 also to repairs to fractures in shell plates G.2 (p&s) and G.3 (p.s) being specially examined and dealt with as necessary next drydocking.

As Now. Subject
Amended.

004677-004680-0352