

"BLUE MARTIN"

Refer Owners' letter of 7.9.65.

SUBMITTED the Owners be informed that provided the American Bureau Certificates for the chain cable in question are available then further testing will not be required. However, it would be advisable to have the cable examined and verified from the A.B. test certificates at Portland by the Society's Surveyors who could assess its suitability for use on the ship prior to its despatch. If this is done and the cable is found in good condition, all that remains would be for the Society's Surveyors to verify the cable with the American Bureau Certificates when it is placed on board the ship.

If you concur and advise us accordingly, we will inform the Seattle Surveyors who will arrange for the examination to be carried out at Portland, Oregon.

The replacement chain cable should be supplied at the earliest possible opportunity as the notation for the Special Survey (when otherwise completed) cannot be assigned until the chain cable is dealt with.

90

17.9.65.



© 2020

Lloyd's Register  
Foundation

004486-004488-0090