

San FranciscoRpt. No. 12187

As the Surveyor is aware the
 S.S. 'David B. Henderson' is not
 a Lloyd's Register classed vessel
 and therefore no first entry
 is available at this office for
 the replacement boiler for

S.S. 'Blue Malin'.

The boiler is one of the
 standard types built in North
 America and first entry reports
 of similar boilers are available
 but the mean drum diameter
 is given as $47\frac{3}{8}$ " diameter of
 tube holes given as $4\frac{1}{32}$ " and
 pitch of tubes as 7".

accept

checked
by cable
23.4.64M.
24.4.64

Surveyor should confirm that
 dimensions given in his report
 are correct and if so give
 name of sister vessel with same
 boiler classed with LR as first
 copies of boiler drawing.

© 2020

Lloyd's Register
Foundation

29/5/64