

15 MAY 1963

EA
Ship's name "BRITISH BIRCH" Port BRS No. 22278

Last survey date 18.4.63

Class is subject to set in shell plates H.17 and J.18 etc.
(p.s.from aft) and G.19, H.18 & 19 (s.s.f) being specially
examined and dealt with as necessary at the next drydocking.

S.R.L. Appendix (as before ~~or none~~)

Nature of present survey (afloat and ~~in drydock~~)

Temporary/deferred repairs to damage caused
by contact.

Recommendation

SUBJECT as above and to buckled and torn soft nose
stem plating in 1st and 2nd below sheer and indented
shell plates (p.s) No.2 in forecastle sheer and
No.3 in 1st below forecastle sheer being specially
examined and dealt with as necessary next drydocking.

As Now Subject.

IN S.R.L.APPENDIX

Shell plates G.18 and H.18 (p.s.f) indented.

© 2020

Lloyd's Register
Foundation