

2

10th January, 1956.

Two

MARSEILLES

11948 As recommended.

"LL" 11941 As recommended. Please furnish particulars of the water ballast capacity of the side tanks and of the altered deep tank forward.

In future similar cases machinery items which do not apply to to the case being reported should be deleted in accordance with the italics in the heading of the Rpt.9 (e.g. "~~Reduction gear~~").



© 2020

Lloyd's Register
Foundation

004512-004519-0086.1