

Ship's Name SS/MS "WEYBURN" Gross tons 2408  
LR 538870

Is there a rpt. 8? NO Port CHITTAGONG Rpt. No. 728

No. of visits 2 First date 22.4.65 Last date 26.4.65

Interim Cert. issued & copy herewith? YES Damage rpt. issued & copy herewith? NO Last rpt. (H.Q. only) CHG. 656

Date of completing rpt. 27.4.65 Surveyed at, if different from Port above

Is a rpt. 9A attached? NO MN - Nature of survey COMPLETION MBS

Survey fees Rs. 295/= Damage fee *10* Expenses Rs. 30/= S.A. fee

12 MAY 1965

DOCKING

Propeller Sea connections Oil gland

Fastenings Wear down of stern bush

Has screw/tube shaft been drawn? Date of examn.

Has shaft been changed? Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner? Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS	(State if oil fired—OF or exhaust gas—EG)	MAIN	PORT	22.4.65	GOOD	each boiler.)
Air heaters			-			
Superheaters			-			
Safety valves			PORT	GOOD		
Mountings, doors and fastenings			PORT	GOOD		
Safety valves adjusted to { Sat Spt			PORT	185 p.s.i.		
Boiler securing arrangements			-			
Main economisers	-	Exhaust gas heated economisers				
Steam heated steam generators	-	Steam generator safety valves adjusted to				
Forced circulating pumps	-	Funnel				
Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?	-	Were oil burning system & remote controls examined in accordance with rules?				

I recommend that the machinery of this ship remain as classed with/without fresh record of MBS 10.64, as previously recommended, subject to any outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

*Arnou*  
MBS 10.64

THURSDAY 20 MAY 1965

*Ross* (A. ROSS)  
Surveyor to Lloyd's Register of Shipping

Lloyd's Register Foundation

FOR CHAIRMAN CLASS. OFFICER

(Await further information)

ALSO FOR

SPL FOR

TRO NOTED BY

SESR

POSTING

HEADER

CERT

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark thus should be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN  
AUXILIARY  
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT


PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
a Generators		l Generators & governors	
b Exciters			
c Air coolers		m Motors	
d Motors			
e Air coolers		n Switchboards & fittings	
f Control gear cables, etc.		o Circuit breakers	
g Insulation resistance		p Cables	
h Insulating oil test		q Insulation resistance	
i Overspeed governors		r Steering gear generators & motors	
j Magnetic couplings		s Navigation light indicators	
k Air gap			

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

Minor wear & tear repairs effected to port boiler.

SRL NO. 233: No items.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2020

Lloyd's Register  
Foundation