

Rpt. 9B

REPORT OF MACHINERY SURVEYS AND REPAIRS

Received London

FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Ship's Name ~~SS~~/MS "PORT WYNHAM"

2 288 0

Gross tons
Port of Registry

Port Melbourne

Date of build

Is there a rpt. 8? No

Rpt. No. 2:288 0

No. of visits

First date

Last date

Interim Cert. issued
& copy herewith?

Damage rpt. issued
& copy herewith?

Last rpt. (H.Q. only)

Date of
completing rpt.

Surveyed at, if different from Port above

Is a rpt. 9A
attached? Yes

MN

Nature of survey ABS

Survey fees

Damage fee

Expenses

See Report 9A.

S.A. fee

DOCKING

Propeller

Sea connections

Oil gland

Fastenings

Wear down of stern bush
(if relined, state clearance
before and after)

Has screw/tube
shaft been drawn?

Date of examn.

Has shaft been
changed?

Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner?

Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, ~~DONKEY OR PRESS~~ (State if oil fired—OF
or exhaust gas—EG) MAIN

Lower O.F. 23-7-65

Air heaters -

Superheaters -

Safety valves Good

Mountings, doors
and fastenings Good

Safety valves { Sat
adjusted to { Sptx 100 P.S.I.

Boiler securing
arrangements Good

Exhaust gas heated economisers
and their safety valves -

Main economisers -

Steam heated
steam generators -

Steam generator safety valves adjusted to -

Forced
circulating pumps -

Funnel Efficient

Have saturated steam pipes in cylindrical boiler
smoke boxes been examined as required by the Rules?

Were oil burning system &
remote controls examined in
accordance with rules? Yes

I recommend that the machinery of this ship remain as classed with/without fresh record of

See Report 9A.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

WEDNESDAY 20 OCT 1965

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

NOTED BY

CESR

SRL

POSTING

HEADER

CERT

004642-004645-0289

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN
AUXILIARY
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
a	Generators	l	Generators & governors
b	Exciters		
c	Air coolers	m	Motors
d	Motors		
e	Air coolers	n	Switchboards & fittings
f	Control gear cables, etc.	o	Circuit breakers
g	Insulation resistance	p	Cables
h	Insulating oil test	q	Insulation resistance
i	Overspeed governors	r	Steering gear generators & motors
j	Magnetic couplings	s	Navigation light indicators
k	Air gap		


PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

In SRL Appendix No.16.

"Instructions Part 3B 1957 amendment No.5 not yet
complied with"

Due to the vessels limited time at this port the
Chief Engineer requested that this item be
deferred till the vessels arrival back at a
U.K. Port.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2020

Lloyd's Register
Foundation