

CARONI

Jacksonville Rpt N^o 1987

Before this report is confirmed, Jacksonville surveyors should be asked to state if:-

Screwshafts have both bronze liners & oil glands, as would appear from this report

Boiler safety valves were adjusted under steam at this time

Also, to explain delay in forwarding this report

JL.

© 2020

9

MAY 1957

Lloyd's Register
Foundation

004684-004692-0041