

Ship's Name SS/MS "ISERNIA"
 Gross tons 580 Port of Registry of Grimsby Port GRIMSBY
 Date of build Is there a rpt. 8? Yes Rpt. No. 30983
 No. of visits First date Last date
 Interim Cert. issued & copy herewith? Damage rpt. issued & copy herewith? Last rpt. (H.Q. only)
 Date of completing rpt. Surveyed at, if different from Port above
 Is a rpt. 9A attached? Yes MN Nature of survey
 Survey fees Damage fee Expenses

S.A. fee

DOCKING

Propeller Good Sea connections All-Good Oil gland -
 Wear down of stern bush (if relined, state clearance before and after) 1/8"
 Fastenings Good
 Has screw tube shaft been drawn? No Date of examn. -
 Has shaft been changed? - Has shaft now fitted been previously used? -
 Has shaft now examined/fitted a continuous liner? - Approved oil gland? -

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN 31/8/65 - Good.

Air heaters Good
 Superheaters Good
 Safety valves Good
 Mountings, doors and fastenings Good
 Safety valves adjusted to { Sat 227 P.S.I.
 { Spt 230 P.S.I.
 Boiler securing arrangements Good
 Main economisers - Exhaust gas heated economisers and their safety valves -
 Steam heated steam generators - Steam generator safety valves adjusted to -
 Forced circulating pumps - Funnel Good
 Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules? Yes Were oil burning system & remote controls examined in accordance with rules? Yes

I recommend that the machinery of this ship remain as classed with/without fresh record of

ALSO FOR

SPL FOR

NOTED BY CESR

POSTING

HEADER

CERT

SEE REPORT 9A.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Surveyor to Lloyd's Register of Shipping


Date of Committee

FRIDAY 22 OCT 1965

G. Beel.

Minute

See Rpt 9A.



2020

Beel

Lloyd's Register Foundation

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark there should be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN
AUXILIARY
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY
Total kW or kVA		Total kW or kVA
a Generators		l Generators & governors
b Exciters		
c Air coolers		m Motors
d Motors		
e Air coolers		n Switchboards & fittings
f Control gear cables, etc.		o Circuit breakers
g Insulation resistance		p Cables
h Insulating oil test		q Insulation resistance Good
i Overspeed governors		r Steering gear generators & motors
j Magnetic couplings		s Navigation light indicators
k Air gap		

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.

