

FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Ship's Name ~~SS/MX~~ "CALTEX LIVERPOOL"

IR 505856

Port of

Gross tons

11,814

Registry London

Port Sydney, N.S.W.

Date of build 11-1952 Is there a rpt. 8? No

Rpt. No. 38208

No. of visits Three

First date 1/10/65

Last date 11/10/65

Interim Cert. issued & copy herewith? Yes

Damage rpt. issued & copy herewith?

Last rpt. (H.Q. only)

Date of completing rpt.

Surveyed at, if different from Port above

Is a rpt. 9A attached? Yes

MN

Nature of survey CSM/MBS

Survey fees

Damage fee

Expenses

See Report 9A

S.A. fee

DOCKING

Propeller

Sea connections

Oil gland

Fastenings

Wear down of stern bush

(if relined, state clearance

before and after)

Has screw/tube shaft been drawn?

Date of examn.

Has shaft been changed?

Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner?

Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG)

MAIN

each boiler.)

Air heaters

P. & S. 6/10/65 - Good

Superheaters

P. & S. - Good

Safety valves

P. & S. - Good

Mountings, doors and fastenings

P. & S. - Good

Safety valves adjusted to { Sat Spt

P. & S. - Good

Boiler securing arrangements

480 p.s.i. - Good

470 p.s.i. - Good

P. & S. - Good

Main economisers Steam heated steam generators

Exhaust gas heated economisers and their safety valves -

Forced circulating pumps

Steam generator safety valves adjusted to -

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?

Funnel - Good
Were oil burning system & remote controls examined in accordance with rules? Yes - Good

I recommend that the machinery of this ship remain as classed with/~~xxxxxx~~ fresh record of

See Report 9A

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Surveyor to Lloyd's Register of Shipping

Date of Committee

MONDAY 15 NOV 1965

(J.H. JAMIESON)

Minute

See Rpt 9A

ALSO FOR

SPL FOR


NOTED BY
TBO
CESR

SEL

POSTING

HEADER

CERT



© 2020
J.H. Jamieson

Lloyd's Register
Foundation

fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

been effected or it is considered that re-examination or repairs should be made before that date a distinguishing mark thus should be inscribed against the item and the circumstances and action taken or recommended described

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN
AUXILIARY
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
a Generators		l Generators & governors	
b Exciters			
c Air coolers		m Motors	
d Motors			
e Air coolers		n Switchboards & fittings	
f Control gear cables, etc.		o Circuit breakers	
g Insulation resistance		p Cables	
h Insulating oil test		q Insulation resistance	
i Overspeed governors		r Steering gear generators & motors	
j Magnetic couplings		s Navigation light indicators	
k Air gap			


PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

S.R.L. Appendix No.16 P. and S. boiler superheater element supports to be specially examined at each Boiler Survey.

Now Done Both boiler supports specially examined and found to remain efficient menatime.

Owners state that new superheater element supports have been ordered and are now being delivered from England, and that they will be fitted at the earliest opportunity.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2020

Lloyd's Register
Foundation