

Received from Chief Ship Surveyor

10 JUN 1959

HIPS NAME

"HUSVIK"

REPORT

Trd.

No.

1571

G<sup>B</sup>

Outstanding Conditions of Class:

SUBJECT to indented side shell plating in 1st & 2nd strakes below sheer in way of No.1 wing cargo tank (p.s.) being specially examined and dealt with as found necessary and to sternframe at scarph (E.W.8,58) being specially examined, next drydocking.

Endorsement of Certificate (As before ~~or None~~)

Signature of Present Survey: (Afloat ~~and in dry dock~~)

Examination afloat after grounding.

Recommendation:

SUBJECT as above, but further ACTION be DEFERRED for examination in dry dock after grounding.

SUBJECT

INSERT IN S.R.L.

Drydocking (grounding).

IN S.R.L. APPENDIX

Indents in shell plating etc. (p & s).  
(Gudgeon bushes eccentric)



© 2021

Lloyd's Register  
Foundation