

Received from Chief Ship Surveyor

NAME

"SAN ELISEO"

REPORT Lon.

No. 143696

Standing Conditions of Class:

SUBJECT to 'A' strake shell plating in way of forward deep tanks (p & s) (fractured) and set in shell plating and structure in way of aft pump room (p.s.) being permanently repaired next drydocking.

Appendix. (~~As before or None~~)e of Present Survey: (~~Afloat and in dry dock~~)

Docking: Further temporary repairs to part deferred items as above.


Amendment:

SUBMITTED record of 'DS 10,60' be assigned, subject to No.1 keel plate from aft (wasted) and to indented keel and adjacent 'A' strake plating (p & s) in way of forward deep tanks also to indented shell plating etc. in way aft pump room (p.s.) being further examined and dealt with as necessary next drydocking and before ship resumes service.

DS 10,60 Subject
Amended.

N.B. Ship now stated to be laid up in Blackwater River.

k (new)



© 2021
Lloyd's Register
Foundation

Amended 21/3/60

004769-004777-0306

and dealt with as necessary next drydocking before resuming trading.