

Should
Repair
from
should
Platin
Cable
which

Give

In day
h

Own

Received from Chief Ship Surveyor.....

17 JAN 1958

ME

"TRITONICA"

REPORT

Sld.

No.

36943

22 JAN 1958

Standing Conditions of Class:

For conditions of class

see previous endorsement dated 11.11.57.

Endorsement of Certificate (As before or None)

Particulars of Present Survey: (Afloat and in dry dock)

Docking: Damage repairs (various causes) and to part of the deferred items as above: Alterations to Nos. 5 & 6 hatchway coamings and to deep tank in accordance with approved plans.

Recommendation:

SUBMITTED record of 'DS 11,57' be assigned subject to set in shell plates G.12 & 13, H.11 & 14 (s.s. from fwd), and set up shell plates keel 2, A.2 (p.s.) A.3 (s.s.) from fwd being examined at the next drydocking and dealt with as necessary by next Special Survey also to distorted hatch coaming plating and deck angles (p.s.), No.2 hatch and starboard No.5 hatch also indented side ballast tank bulkhead plating portside of Nos. 2 & 4 hatches being repaired at next Special Survey, without other conditions.

DS 11,57 Subject
Without.

Blk (new)

Has a

SAR.
8-1-58

[P.T.O.]

004861-004865-6191

AMEND R.B. to -

6BHs.

DB pt W.B. pt O.F; DTf 565t.

FREEBOARD SURVEYORS TO NOTE this report.

IT IS FURTHER SUBMITTED the Surveyors be
requested to furnish a plan indicating the alterations now
effected. *to hatchway coaming.*

IN L.O.E.

(Main structure partly of P.403 Steel)



© 2020

Lloyd's Register
Foundation

Repair
from Repairs
should be st
Plating is dri
Cables are r
which is to b

Give dates a

In damage c

his serv

Owners

EXAMINAT

DAMAGE

DAMAGE

DAMAGE

REPAIR

DAMAGE

MMAR

tenewed

temoved

aired o

Has a Surv

If so, is the

GENERAL