


TRANSLATION OF CERTIFICATE ISSUED

LLOYD'S REGISTER OF SHIPPING



Port MADRID

12

12th July, 1958

B.18 (MAD)

This is to Certify that

G. DIXON

the undersigned Surveyor to this Society did at the request of

Talleres Mercier, S.A., Zaragoza, attended their works on the 10th July, 1958, and previous dates for the survey during construction of a Waste Heat Boiler, Markers N° 95 ordered by Astilleros de Cadiz, S.A., and intended for the M/T "BONIFAZ" (T-7), Yard N° 47.

This Boiler has been made in accordance with Plans Nos. S.278, 1905, 1912, N427 and 1916 approved 23.1.57.

The materials have been tested by the Surveyors to LLOYD'S REGISTER and the scantlings are in accordance with the Rules for a working pressure of 12 Kgs/sq.cm. and the workmanship is good. The boiler having been tested in my presence on the 10th July, 1958, by hydraulic pressure to 24 Kgs/sq.cm. showed no signs of weakness and was found tight and sound at that pressure. Working pressure not to exceed TWELVE KGS/SQ.CM.

Mark on Boiler: -

N° 18 (MAD)
LLOYD'S TEST
24 Kgs.
W.P. 12 Kgs.
10.7.58. G.D.

*approved for 16 Kgs
Letter book 26/2/59*

Other marks are as follows: -

INLET HEADER LLOYD'S N° 5099
LLOYD'S TEST 50 Kgs. 11.6.58 R.W.S.

OUTLET HEADER LLOYD'S N° 5098
LLOYD'S TEST 50 Kgs. 11.6.58. R.W.S.

All tube elements, including spares, have been separately tested by hydraulic pressure to 50 Kgs/sq.cm.

G. Dixon
Surveyor to Lloyd's Register
sgd) G. Dixon

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."