

13th May, 1960.

AMSTERDAM

23345, 69, 76, 78 - As recommended.

23366 "HAUSBORG" - As recommended except that the class has been continued subject to:-

1. The main engine No. 5 starboard column forward side of the top flange (Metalock 5.59) being re-examined by March, 1961.
2. The main engine No. 5 top cylinder cover being specially examined by March, 1961.
3. The No. 6 top and bottom cylinder covers being specially examined and dealt with as necessary by March, 1961.

Please issue an amended interim certificate incorporating these conditions of class.

With regard to the No. 5 starboard column, it is considered that this part should be again inspected having regard to the fact that your examination is the first one after the repair had been carried out.



© 2020

Lloyd's Register
Foundation

004887-004892-0096